

Roof repair of the school building, Ochiul Alb

The flat roof leaked and let rain water and snow penetrate. The walls and ceilings were always wet and moldy. Under these circumstances, the school was in danger to close a part of the building.



Thanks to the financial support of KINDERMISSIONSWERK children could continue their studies as from September 1st.

August 2011